			Which DROP Models Were Affected?						
Firmware Version	**Date Implemented**	**Firmware Notes**	**D1**	**D2**	**D2HS**	**D2FW**	**D3**	**D3FW**	**Latest BLE Version**
1.56	5/24/2021	Fixes DROP settings not being maintained after removing battery	X	X	X	X	X	X	1.05
1.55	1/13/2021	Fixes issue where RH not reading correctly at low battery levels	X	X	X	X	X	X	1.05
		Updates Bluetooth Profile	X	X	X	X	X	X	
		Allows Connection to New Kestrel LINK app	X	X	X	X	X	X	
1.54	10/11/2016	Initial Release							1.03